84-05

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 9

In the Matter of NEVILLE CHEMICAL COMPANY, ORDER Docket No. 84-05 Respondent. PROCEEDING UNDER SECTION 3013 OF THE RESOURCE CONSERVATION AND RECOVERY ACT, AS AMENDED (42 USC \$6934)

JURISDICTION

The following Order is issued on this date to Neville Chemical Company (Respondent), pursuant to the authority [19] vested in the Administrator of the United States Environmental 20 Protection Agency (EPA) by \$3013 of the Resource Conservation and Recovery Act, as amended, (RCRA), 42 USC \$6934, and 22: redelegated to the Director, Toxics and Waste Management 23 Division, EPA, Region 9.

FINDINGS OF FACTS

25 FACILITY AREA

2

3

G

8

9

10

11

12

13

14

15

16

17

24

26

27

28

Respondent owns and operates a facility located at 12800 East Imperial Highway, Santa Fe Springs, California (the "facility").

2. The facility is engaged in, among other things, the production of chlorinated paraffins. Respondent uses dichlorobenzene (DCB) as a cleaning solvent in its production process.

- 3. Dichlorobenzenes (including ortho-, para-, meta-, and mixed DCB) are hazardous wastes as defined in \$1004(5) of RCRA, 42 USC \$6903(5). The term DCB, as used in this Order, means one or a combination of the following compounds:
 - 1,2 dichlorobenzene (a.k.a. ortho-), 1,3 dichlorobenzene (a.k.a. meta-), and 1,4 dichlorobenzene (a.k.a. para-).
- 4. On August 15, 1980, Respondent notified EPA, pursuant to \$3010 of RCRA, 42 USC \$6930, that it generates hazardous wastes at the facility, including halogenated spent solvents and corrosives. DCB is listed, at 40 CFR \$261.31, as a hazardous waste constituent of spent halogenated solvents.
- 5. Respondent produces chlorinated paraffins at the facility by charging paraffin into a reactor, injecting chlorine at a controlled rate, and chlorinating the product according to customer specifications. The raw materials used to produce chlorinated paraffins include liquid chlorine, paraffin, carbon tetrachloride, and other minor materials. Chlorinated paraffins are used in traffic paints, rubber belts, and lubricating oils.
- 6. In one type of reaction used to produce chlorinated paraffins at the facility, wax is diluted with carbon tetrachloride, and chlorinated up to 70% at approximately 70°C (158°F). The solution is then stripped by heat and

placed under a vacuum to remove the carbon tetrachloride.

DCB is used in the production process as a cleaning solvent to strip the residues in the 70% chlorinated paraffin process line. Spent DCB is collected in a storage tank to be reclaimed by distillation at a later date.

- 7. Distillation of DCB at the facility involves the following process:
 - Add caustic soda (pH=14) to still;
 - Transfer DCB to still;

G

24!

- Heat DCB to 120°C/248°F;
- Inject low pressure steam (around 100°C/212°F);
- 5. Steam-strip DCB (DCB and water are condensed out); and
- 6. Trailifer to clean DCB storage tank.

Still-bottom residues and condensate are then transferred into 55 gallon drums for off-site disposal. Reclaimed DCB is reused on-site.

- On August 5, 1983, EPA Region 9 conducted an inspection of the facility under the authorities of the Resource Conservation and Recovery Act (RCRA), 42 USC 6901 et seq., and the Toxic Substances Control Act (TSCA), 15 USC 2601 et seq. The inspection established the possibility that dioxins, furans and/or related compounds were being produced as contaminants of DCB in the facility's DCB distillation process. The specific contaminants of concern to EPA were tetrachlorodibenzodioxin (TCDD) and tetrachlorodibenzofuran (TCDF). During the inspection, the EPA inspector observed spilled still-bottom residues on the ground in the vicinity of the facility's stills.
- 9. On November 2, 1983, EPA representatives collected samples of on-site and perimeter soil, uncontained distillation

residue, and drummed still bottom waste at the facility to determine whether dioxins, furans and/or related compounds were being created and released to the environment as a result of the distillation of DCB. The primary compounds detected on-site in soil and spilled residue samples are shown below.

1.

26 11.

(All units in parts per million (ppm), except for TCDF data.)

Sample Description	Still Residue	On-Site Perimeter Soil	On-site Soil
Sample Number	Y-2858	Y-2857	Y~2856
TCDF	39 ppb	25 ppb	13 ppb
2,4,6-trichlorophenol	100 K*	100 K	-
1,2,4-trichlorobenzene	100 K	100 K	14
Hexachlorobenzene	100 K	100 K	1
1,2-dichlorobenzene	1100	100 K	22
1,3-dichlorobenzene	690	100 K	42
1,4-dichlorobenzene	250	- -	10 K

*The use of K indicated that a compound was present in the sample at a value less than the detection limit preceding K.

Other compounds detected in the soil and spilled residue samples included various chlorinated benzenes and phenols.

Dioxins and furans can be created from the pyrolysis of chlorinated benzenes. Reactions between chlorophenols and chlorobenzenes may also lead to furan formation.

TCDF may be formed under conditions similar to those used by Respondent at the facility. The analytical data summarized in paragraph 9 above confirms that chlorophenols,

chlorobenzenes and TCDF is present in the facility's DCB still residue.

EPA has expressed its concern with the substantial risk 12. to human health and the environment posed by dioxins and furans.

2

3

4

5

G

8

9

10

11

12

13

14

15

17

18

191

20

21

22

23

24

25

26

27

28

The tetra-, penta-, and hexachlorodibenzodioxins and -dibenzofurans (CDDs and CDFs) are of particular concern based upon known or expected toxicity. (48 FR 14514, April 4, 1983.)

- 13. Hu...an exposure to DCB is reported to cause hemolytic anemia and liver necrosis, and 1,4 DCB has been found in human adipose tissue. In addition, DCB is toxic to nonhuman mammals, birds, and aquatic orgainisms. DCB is metabolized by mammals, including humans, to various dichlorophenols, some of which are as toxic as DCB.
- On March 12, 1984, Mark Bradford, an employee of EPA's 16||14. contractor Ecology and Environment, Inc., contacted John Ferguson, the plant manager, to gain access to the facility. Mr. Bradford advised Mr. Ferguson that he was requesting access to the facility pursuant to EPA statutory authority and that the purpose of his visit was to clarify and update a plot plan of the facility provided by Respondent during a previous site visit. An updated plot plan would facilitate preparation by EPA of a sampling plan to fully characterize site contamination. Mr. Ferguson refused site access to Mr. Bradford. Mr. Ferguson also refused to advise Mr. Bradford of facility changes since preparation of the original plot plan.

1 115. On March 12, 1984, after being refused access to the facility, Mr. Bradford advised Steve Simanonck, an employee of EPA Region 9, of Respondent's refusal to allow site access or provide the necessary information to update the plot plan.

Mr. Simanonok contacted Respondent's headquarters office located in Pittsburgh, Pennsylvania and spoke with Tom McKnight, corporate counsel. After much discussion, Mr. McKnight agreed to allow Mr. Bradford to inspect the facility the following day (March 13, 1984) for the purpose of updating and clarifying the plot plan. Mr. McKnight advised Mr. Simanonok that Mr. Bradford would be given access to the facility on the following morning.

- On March 13, 1984, being advised by EPA that the Respondent 14 16. had agreed to allow access, Mr. Bradford contacted Mr. Ferguson to arrange a site visit that same day. Despite 17 prior assurances to Mr. Simanonok, Respondent again refused access to Mr. Bradford.
- 19 17. On March 13, 1984, the California Department of Health 20 Services (DOHS) and the Los Angeles County Department 21 of Health Services (LA DOHS) inspected the facility and 22 surrounding area. Based upon this inspection, DOHS and LA 23 DOHS jointly issued a Notice of Violation to Respondent on 24 March 13, 1984. The Notice of Violation directed Respondent 25 to initiate the following remedial actions:
 - Discontinue any further unlawful discharges of hazardous waste forthwith.

27

26

2

3

5

6

8

9

10

11

12

13

15

161

18

- Remove and legally dispose of all hazardous waste accumulated along the west side of the facility adjoining the railroad tracks.
- Provide adequate controls to prevent runoff and emissions of contaminated materials from the subject facility.
- Institute air monitoring to determine the presence and concentration of toxic emissions from the subject This shall include a monitoring station at the adjacent residential area west of the plant.
- Surface soil sampling in adjoining areas shall be 5) undertaken to determine the extent to which hazardous materials have migrated from the subject facility. Soil sampling shall be conducted in the presence of a representative of this office and the analytical results submitted to this Department by March 22, 1984.
- Submit a comprehensive site characterization and cleanup plan to this office by March 22, 1984.

13 OFF-SITE AREA

1

2

3

4

5

6

7

8

9

10

11

12

15

17

18

19

201

21

22

23

24

25

26

27

- 14 18. Respondent also owns a triangular-shaped parcel located adjacent to and south of the facility ("off-site area").
- 16 19. EPA has received information indicating that the Respondent has disposed of hazardous wastes at the off-site area. off-site area may also be known as the "Kalico dump".) Information pertaining to Respondent's disposal activity at the off-site area includes:
 - On or about June 11 1970, Robert Hartley, an employee of the Los Angeles Department of County Engineer, inspected the facility and observed discharges from the facility to the off-site area. The discharges included ferric chloride leaking from air pollution equipment and liquid waste from the facility's cooling tower (laboratory analysis of this waste showed a pH of 2.2 and numerous inorganic constituents). The County Engineer also

- On or about March 17, 1980, Mr. L. R. Bitner, plant manager of the facility, completed an Industrial Waste Survey that was filed with the Abandoned Site Project of the California Department of Health Services. Mr. Bitner reported that prior operations at the facility included disposal of waste chlorinated hydrocarbon that was discharged or dumped onto plant property.
- 10 20. The hazardous wastes and contaminants described in paragraphs 9 and 19 above are being treated and disposed of at the facility in such manner that they are being released and discharged from the facility onto the soil and thus may be carried off-site via airborne releases and/or surface runoff.

DETERMINATION

On the basis of the information recited above and all other information available, EPA has determined that hazardous wastes are being stored, treated or disposed of at the facility and are present at the facility.

EPA has further determined that hazardous wastes have been released from the facility and may present a substantial hazard to human health or the environment.

EPA has further determined that Respondent is a current owner/operator responsible for conducting the actions ordered herein, which are necessary to protect human health and the environment.

27 28

2

3

5

6

7

8

9

11

12

13

14

15

16

17

18

1911

20

21

22

23

24

25

ORDER

Based upon the foregoing Determination and Findings of Fact, Respondent, Neville Chemical Company, is hereby ordered to submit a proposal to EPA for the sampling, analysis, reporting and monitoring of the hazardous wastes present on or being released from the facility, and to implement such proposal, once approved by EPA. The proposal shall include, at a minimum, the following elements:

1. FACILITY AREA SOIL SAMPLING

A plan to determine the lateral and vertical distribution of hazardous wastes and contaminants, including dioxins and furans, in soils both on and beyond the facility.

The plan shall identify soil sampling locations and include the <u>discrete</u> sampling of surface soils and the <u>composite</u> sampling of subsurface soils at depths of 6" to 12", 12" to 24", and 24" to 36". (Respondent may elect to obtain additional composite samples at greater depths.)

2. DUST SAMPLING

A plan to determine the distribution of soil particulate upon and immediately adjacent to the facility. This plan shall include the collection of particulate using a High Efficiency Particulate Absolute filtration system (HEPA vacuum) which provides a 99.97% particulate efficiency. These samples should be obtained during dry conditions to prevent failure of the HEPA vacuum if used on wet material. These samples shall be obtained at the following locations:

a) The roof of the building immediately east of the facility.

1 2

6

9

10 11

10

13

15

161

17

18

19

20

21

22

23

24

3. OFF-SITE AREA 14

location.

d)

A plan to determine the lateral and vertical distribution of hazardous wastes disposed at this location. Since exact disposal locations are unknown, the off-site sampling plan should be based upon a preliminary assessment of past disposal activities. The preliminary assessment which shall include, at a minimum:

The area between the Imperial Highway entrance and the

The area immediately south of the facility's DCB stills.

The length of the western boundary of the facility.

At each of the above sampling locations, sufficient

for laboratory analysis employing a detection of

1 part per billion (8-ounce volume). In addition

sufficient volume must be obtained to provide EPA

with duplicate samples (16 ounces total). In order

to prevent cross-contamination, the HEPA sample hose

and inner bag must be replaced between each sample

sample volume shall be obtained to provide capability

processing area of the facility.

- A review of state and local agency files;
- A review of historical aerial photographs;
- Interviews with current and former plant employees;
- Identification of former owners and operators; đ.
- Identification of industrial activities, chemical processes, production volumes, and anticipated waste streams from current and former owners and operators at the facility; and

25

26

f. Identification of former industrial and or chemical process areas, including probable locat ins of waste pits, ponds, lagoons, trenches, seepage and/or septic systems, buried drums, and conveyance structures from the facility and/or other adjacent facilities.

The preliminary assessment shall include a comprehensive evaluation of all items contained in items (a) through (f) above. Respondent shall retain records of each specific reference obtained, and shall make these records available to EPA for inspection or submittal to EPA upon request.

4. SAMPLING QUALITY CONTROL

Quality control protocols for the sampling program including:

- a) Equipment
- b) Decontamination of sampling equipment
- c) Sample handling and decontamination
- d) Procedure for packing hazardous waste samples
- e) Personnel and site safety procedures
- f) Sample identification
 - g) Chain-of-custody
 - h) Identification of persons conducting the sampling

22| 5. DUPLICATE SAMPLES

A plan for retaining, identifying, maintaining and submitting to EPA, upon request, duplicates of all samples taken pursuant to this Order. These duplicate samples shall be collected and identified in the identical manner as those collected by the Respondent.

281

3.

5.

G

7

8

9

10

11

12

13

14

15

16

17

181

19

20

21

23

24

25

26

6. ANALYTICAL AND QUALITY CONTROL PROTOCOLS

11!

Respondent may elect to perform soil sample a plysis in phases. For example, Respondent may initially analyze the discrete surface soils and the composite subsurface soils obtained at depths of 6" to 12". If Respondent elects phased analysis, Respondent shall submit the initial analytical results to EPA immediately upon Respondent's receipt of such results, and obtain EPA direction whether analy is of subsurface composite samples at depths of 12" to 24" and 24" to 36" require analysis.

Respondent's proposal shall state whether phased analysis, as discussed above, will be utilized.

In preparing the plan specified in paragraphs 1 through 6 of this Order, the facility shall refer to the attached document "Determination of 2,3,7,8- TCDD in Soil and Sediment", May, 1983 (Attachment A). Respondent shall employ equivalent techniques and procedures in accomplishing the tasks required under this Order. Respondent shall modify, after consultation with the laboratory, these analytical procedures to include analysis for the following compounds:

- Total Tetrachlorodibenzofuran (TCDF)
- 2,3,7,8- TCDF
- Total Pentachlorodobenzofuran (PCDF)
- Total Hexachlorodibenzofuran (HCDF)
- Total Tetrachlorodibenzodioxin (TCDD)
- 2,3,7,8- TCDD
- Total Pentachlorodibenzodioxin (PCDD)
- Total Hexachlorodibenzodioxin (HCDD)

In addition, Respondent shall perform the initial analyses for all organic and inorganic constituents on the Hazardous Subscance List (Attachment B).

3

- 1. Facility Area Soil and Dust Sampling (Items 1, 2, 4, 5 & 6 of this Order)
 - submitted by Respondent to Betsy Curnow, Environmental Protection Agency, at the address listed below, within 30 days of the effective date of this Order. The proposed plan shall be subject to review, modification and approval by EPA.
 - b. Respondent shall complete all work, including sample analyses, as set forth in the approved plan within
 45 days after receipt of EPA approval of the proposal.
 - c. Respondent shall submit a written report to EPA describing the data collected and findings made within 60 days after receipt of EPA approval of the proposal.
- 2. Off-Site Area (Items 3,4,5 & 6)
 - a. Respondent shall submit to EPA its preliminary assessment of the designated off-site area within 45 days of the effective date of this Order.
 - b. Respondent shall submit a sampling and analysis plan based upon the preliminary assessment of the designated off-site area within 60 days of the effective date of this Order. The proposed plan shall be subject to review, modification and approval of EPA.
 - c. Respondent shall complete all work, including sample analyses, as set forth in the approved plan within 45 days after receipt of EPA approval of the proposal.

d. Respondent shall submit to EPA a written report describing the data collected and findings made within 60 days after receipt of EPA approval of the proposal.

Based upon the data generated by the sampling and analysis program, EPA may order additional sampling, analysis, reporting and monitoring to fully ascertain the nature and extent of the hazard.

Employees and authorized representatives of EPA and the State of California shall be granted access to Respondent's facility for the purpose of verifying compliance with the provisions of this Order.

EFFECTIVE DATE - OPPORTUNITY TO CONFER

This Order is effective immediately upon receipt by Respondent, and all times for performance of response activities shall be calculated from that date.

Under the provisions of RCRA, Respondent is entitled to request a conference with EPA. At any conference held pursuant to Respondent's request, Respondent may appear in person and by attorney or other representatives for the purpose of presenting any objections, defenses or contentions which Respondent may have regarding this Order. Any objection, defense or contention which Respondent may make should be in writing, signed and forwarded to the contact person named below on or before the date on which you are required to submit the proposal. The opportunity to confer does not alter the requirement for submittal of the plan within thirty days of the effective date of this Order.

11!

LIABILITY

If EPA determines that Respondent is not able to conduct the activities ordered herein, or if actions carried out are deemed unsatisfactory, then EPA may conduct Each actions deemed reasonable by EPA to ascertain the nature and extent of the hazard. Respondent may then be ordered to reimburse EPA for the costs of such activity pursuant to \$3013(d) of RCRA. the event Respondent fails or refuses to comply with the terms and provisions of this Order, EPA may commence a civil action, pursuant to \$3013(e) of RCRA, to require compliance with such Order and assess civil penalties not to exceed \$5,000 for each day that Respondent fails or refuses to comply.

It is so ordered on this 28 day of March, 1984. Order shall become effective immediately.

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

HARRY SERAYDARIAN DIRECTOR, TOXICS AND WASTE MANAGEMENT DIVISION

20

1

2

3

4

5

6

7

8

9

10

11

13

15

16

17

18

19

Contact Person:

22|| Betsy Curnow Project Officer

23 Environmental Protection Agency, Region 9

215 Fremont Street

San Francisco, California 94105

(415) 974-8143

25 26

27